

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	
作業ID	作業番号	作業指示	作業アイテム	日時	時刻	標準時間	経過時間	処理項目	判定結果	最終判定結果	画像ロフのファイル名	コメント	船庫データ/船庫名	回転角度/部品シリアル	チェックポイント	チェックポイント船庫	回転角度	マッチング時間	色認識精度	質感精度		
K60801	Y29800101	E123456	Work_1	Item_1	2019/7/9	6:53:57	30	6 S/N	OK	OK	OK_Y298000101_K60801_Work_1_Item_1_20190709_065357.jpg		20180901A-01ABCA	20180901A-01ABC								
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:53:58	5	1 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065357.jpg	ABC	0.93869	0	1	0.979228	-1	201	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:53:58	5	1 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065357.jpg	ABC	0.93869	0	2	0.971398	-1	201	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:53:58	5	1 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065357.jpg	ABC	0.93869	0	3	0.974993	-1	201	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:53:58	5	1 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065357.jpg	ABC	0.93869	0	4	0.926922	-1	201	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_2	2019/7/9	6:54:00	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_2_20190709_065359.jpg	ABC	0.936428	0	1	0	0	170	0.997314	0	0	
K60801	Y29800101	E123456	Work_2	Item_2	2019/7/9	6:54:00	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_2_20190709_065359.jpg	ABC	0.936428	0	2	0.964587	1	170	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:54:19	30	4 S/N	OK	OK	OK_Y298000102_K60801_Work_1_Item_1_20190709_065419.jpg		20180901A-01ABCA	20180901A-01ABC								
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:54:21	5	1 Matching	OK	OK	OK_Y298000102_K60801_Work_2_Item_1_20190709_065420.jpg	0.937103		0	1	0.979849	-1	196	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:54:21	5	1 Matching	OK	OK	OK_Y298000102_K60801_Work_2_Item_1_20190709_065420.jpg	0.937103		0	2	0.972087	-1	196	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:54:21	5	1 Matching	OK	OK	OK_Y298000102_K60801_Work_2_Item_1_20190709_065420.jpg	0.937103		0	3	0.975003	-1	196	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:54:21	5	1 Matching	OK	OK	OK_Y298000102_K60801_Work_2_Item_1_20190709_065420.jpg	0.937103		0	4	0.92631	-1	196	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_2	2019/7/9	6:54:22	5	0 Matching	OK	OK	OK_Y298000102_K60801_Work_2_Item_2_20190709_065422.jpg	0.936231		0	1	0	0	168	0.997314	0	0	
K60801	Y29800101	E123456	Work_2	Item_2	2019/7/9	6:54:22	5	0 Matching	OK	OK	OK_Y298000102_K60801_Work_2_Item_2_20190709_065422.jpg	0.936231		0	2	0.963395	1	168	0	0	0	
K60801	YH76000202	E123456	Work_1	Item_1	2019/7/9	6:54:47	30	6 S/N	OK	OK	OK_YH76000202_K60801_Work_1_Item_1_20190709_065447.jpg		20180901A-01ABCA	20180901A-01ABC								
K60801	YH76000202	E123456	Work_2	Item_1	2019/7/9	6:54:48	5	1 Matching	OK	OK	OK_YH76000202_K60801_Work_2_Item_1_20190709_065447.jpg	0.935804		0	1	0.978398	-1	201	0	0	0	
K60801	YH76000202	E123456	Work_2	Item_1	2019/7/9	6:54:48	5	1 Matching	OK	OK	OK_YH76000202_K60801_Work_2_Item_1_20190709_065447.jpg	0.935804		0	2	0.97227	-1	201	0	0	0	
K60801	YH76000202	E123456	Work_2	Item_1	2019/7/9	6:54:48	5	1 Matching	OK	OK	OK_YH76000202_K60801_Work_2_Item_1_20190709_065447.jpg	0.935804		0	3	0.974677	-1	201	0	0	0	
K60801	YH76000202	E123456	Work_2	Item_1	2019/7/9	6:54:49	5	1 Matching	OK	OK	OK_YH76000202_K60801_Work_2_Item_1_20190709_065447.jpg	0.935804		0	4	0.921683	-1	201	0	0	0	
K60801	YH76000202	E123456	Work_2	Item_2	2019/7/9	6:54:50	5	0 Matching	OK	OK	OK_YH76000202_K60801_Work_2_Item_2_20190709_065449.jpg	0.93649		0	1	0	0	159	0.996093	0	0	
K60801	YH76000202	E123456	Work_2	Item_2	2019/7/9	6:54:50	5	0 Matching	OK	OK	OK_YH76000202_K60801_Work_2_Item_2_20190709_065449.jpg	0.93649		0	2	0.964338	0	159	0	0	0	
K60801	YH76000203	E123456	Work_1	Item_1	2019/7/9	6:55:20	30	14 S/N	OK	OK	OK_YH76000203_K60801_Work_1_Item_1_20190709_065520.jpg		20180901A-01ABCA	20180901A-01ABC								
K60801	YH76000203	E123456	Work_2	Item_1	2019/7/9	6:55:22	5	1 Matching	OK	OK	OK_YH76000203_K60801_Work_2_Item_1_20190709_065521.jpg	0.939527		0	1	0.977113	-1	214	0	0	0	
K60801	YH76000203	E123456	Work_2	Item_1	2019/7/9	6:55:22	5	1 Matching	OK	OK	OK_YH76000203_K60801_Work_2_Item_1_20190709_065521.jpg	0.939527		0	2	0.966552	-1	214	0	0	0	
K60801	YH76000203	E123456	Work_2	Item_1	2019/7/9	6:55:22	5	1 Matching	OK	OK	OK_YH76000203_K60801_Work_2_Item_1_20190709_065521.jpg	0.939527		0	3	0.966784	-1	214	0	0	0	
K60801	YH76000203	E123456	Work_2	Item_1	2019/7/9	6:55:22	5	1 Matching	OK	OK	OK_YH76000203_K60801_Work_2_Item_1_20190709_065521.jpg	0.939527		0	4	0.91325	-1	214	0	0	0	
K60801	YH76000203	E123456	Work_2	Item_2	2019/7/9	6:55:31	5	8 Matching	NG	NG	NG_YH76000203_K60801_Work_2_Item_2_20190709_065531.jpg	0.903513		-1	1	0	0	166	0.510623	0	0	
K60801	YH76000203	E123456	Work_2	Item_2	2019/7/9	6:55:31	5	8 Matching	NG	NG	NG_YH76000203_K60801_Work_2_Item_2_20190709_065531.jpg	0.903513		-1	2	0.678779	-9	166	0	0	0	
K60801	YH76000203	E123456	Work_2	Item_2	2019/7/9	6:55:55		Start														
K60801	YH76000203	E123456	Work_2	Item_2	2019/7/9	6:55:56	5	0 Matching	OK	OK	OK_YH76000203_K60801_Work_2_Item_2_20190709_065555.jpg	0.952399		0	1	0	0	173	0.997802	0	0	
K60801	YH76000203	E123456	Work_2	Item_2	2019/7/9	6:55:56	5	0 Matching	OK	OK	OK_YH76000203_K60801_Work_2_Item_2_20190709_065555.jpg	0.952399		0	2	0.96358	-2	173	0	0	0	
K60801	Y29800101	E123456	Work_1	Item_1	2019/7/9	6:56:29	30	6 S/N	OK	OK	OK_Y298000101_K60801_Work_1_Item_1_20190709_065629.jpg		20180901A-01ABCA	20180901A-01ABC								
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:56:39	5	8 Matching	NG	NG	NG_Y298000101_K60801_Work_2_Item_1_20190709_065638.jpg	0.894392		0	1	0.652737	-2	190	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:56:39	5	8 Matching	NG	NG	NG_Y298000101_K60801_Work_2_Item_1_20190709_065638.jpg	0.894392		0	2	0.4999	0	190	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:56:39	5	8 Matching	NG	NG	NG_Y298000101_K60801_Work_2_Item_1_20190709_065638.jpg	0.894392		0	3	0.765884	0	190	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:56:39	5	8 Matching	NG	NG	NG_Y298000101_K60801_Work_2_Item_1_20190709_065638.jpg	0.894392		0	4	0.86601	0	190	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:57:11		Start														
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:57:12	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065711.jpg	0.932694		0	1	0.978105	0	194	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:57:12	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065711.jpg	0.932694		0	2	0.945639	0	194	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:57:12	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065711.jpg	0.932694		0	3	0.934842	0	194	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_1	2019/7/9	6:57:12	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_1_20190709_065711.jpg	0.932694		0	4	0.946352	0	194	0	0	0	
K60801	Y29800101	E123456	Work_2	Item_2	2019/7/9	6:57:13	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_2_20190709_065712.jpg	0.905595		0	1	0	0	170	0.999267	0	0	
K60801	Y29800101	E123456	Work_2	Item_2	2019/7/9	6:57:13	5	0 Matching	OK	OK	OK_Y298000101_K60801_Work_2_Item_2_20190709_065712.jpg	0.905595		0	2	0.968529	-1	170	0	0	0	
K60801	Y29800101	E123456	Work_1	Item_1	2019/7/9	6:57:30		log out														

※本製品のCSVログの活用イメージです。表示形式が実際のもものと異なる可能性があります。